



PMG SIGNATURE 512 DAC

RELEASE NOTES

Version **DAC:** 2.5.4
 Streamer: 2.1.98380d
Date 09/25/2025
File pmg_dac_v2.5.4.bin

Description

This load improves streamer initialization, fixes several UI issues, improves Wi-Fi provisioning, and gives better control of Menu volume settings (fixed volume, max volume).

New Features

- Streamer icon input lock will blink green during initialization
 - When the streamer is initializing, the streamer lock icon will blink green after the streamer gets Internet connection and the streaming services are first initializing. During this period, the PMG DAC streamer may not appear on streaming apps such as Spotify, Roon, etc... The green icon lock will blink for about 30 to 60 seconds. At this point, the streaming services should appear. Note that some services come up faster than others, and when the PMG DAC Streamer appears in your streaming app it is ready to use, you don't have to wait for the green input lock icon to stop blinking.

Fixes

- Fixed issue where fonts on the screen become corrupted
 - Added interactive volume control for fixed volume and max volume
 - Improved Wi-Fi provisioning and UI Dialog interaction
 - Fixes for volume not behaving properly when changing inputs
 - Menu timeout is turned off during streamer FW updates
 - Fixes for trigger menus not working
 - Some settings were not properly restored on power on
 - Added pop-up to indicate a reboot after a factory reset
 - A factory reset will delete all saved Wi-Fi connections/ SSIDs on the streamer
 - Factory reset will wait until the streamer has completed factory reset before rebooting the unit
 - Improved factory reset dialog
-

Version	DAC: 2.5.0 Streamer: 1.16.121bc4
Date	08/21/2025
File	pmg_dac_v2.5.0.bin

Description

Original release.