



STELLARGOLD PRE **RELEASE NOTES**

Version 2.3.0
Date 12/14/2023
File stgold_pre_v2.3.0.bin

Description

Bug fixes.

Fixes

- Additional fixes for display being cut-off on the right
 - Added balance IR control
 - Fixed IR power codes
 - Fixed bug in trigger event
 - Set trigger on by default and factory reset
-

Version 2.2.0
Date 10/24/2023
File stgold_pre_v2.2.0.bin

Description

Fixes many beta issues.

Changed the binary file name to stgold_pre_vX.Y.X.bin.

Fixes

- STLR-1132 The display is partially obscured on the right-hand side
 - STLR-1147 Can't get to Factory Reset menu
 - STLR-1148 Issues with Remote performance
 - STLR-1172 Triggers aren't working
 - STLR-1179 Add balance control from IR
-

Version 2.1.4
Date 10/13/2023
File stellar_pre_v2.4.6.bin

Description

Fixes issues in beta with IR performance.

Fixes

- STLR-1148 Issues with Remote performance

Known Issues

- STLR-1132 The display is partially obscured on the right hand side
- STLR-1134 Can't tell when you are in sub-menus

Version	2.1.2
Date	09/25/2023
File	stellar_pre_v2.1.2.bin

Description

Initial beta release.

Fixes

Initial Release