



STELLARGOLD PRE **RELEASE NOTES**

Version 2.4.0
Date 9/4/2024
File stgold_pre_v2.4.0.bin
Image.bin

Description

Bug fixes.

Fixes

- Fixed Volume not working when changing inputs
- Some settings not restored after power cycle

Version 2.3.0
Date 12/14/2023
File stgold_pre_v2.3.0.bin

Description

Bug fixes.

Fixes

- Additional fixes for display being cut-off on the right
- Added balance IR control
- Fixed IR power codes
- Fixed bug in trigger event
- Set trigger on by default and factory reset

Version 2.2.0
Date 10/24/2023
File stgold_pre_v2.2.0.bin

Description

Fixes many beta issues.

Changed the binary file name to stgold_pre_vX.Y.X.bin.

Fixes

- STLR-1132 The display is partially obscured on the right-hand side
- STLR-1147 Can't get to Factory Reset menu
- STLR-1148 Issues with Remote performance
- STLR-1172 Triggers aren't working
- STLR-1179 Add balance control from IR

| | |
|----------------|------------------------|
| Version | 2.1.4 |
| Date | 10/13/2023 |
| File | stellar_pre_v2.4.6.bin |

Description

Fixes issues in beta with IR performance.

Fixes

- STLR-1148 Issues with Remote performance

Known Issues

- STLR-1132 The display is partially obscured on the right hand side
- STLR-1134 Can't tell when you are in sub-menus

| | |
|----------------|------------------------|
| Version | 2.1.2 |
| Date | 09/25/2023 |
| File | stellar_pre_v2.1.2.bin |

Description

Initial beta release.

Fixes

Initial Release